BUCHER automation

Known Open Issues in JetSym Version 6.1.1

- ID 18909

  Parameter information can only be displayed in the first line.
  Description: When a function call is wrapped across multiple lines, parameter information can only be displayed if the cursor is in the first line of the function call.
- ID 19520

  Comma in comments shifts parameter information.
  Description: Using commas in single-line code comments may cause parameter information to be displayed with incorrectly aligned parameters.
- ID 19433

  ALT-selected lines in the editor cannot be indented or outdented using keyboard shortcuts.
  Description: Code blocks selected using ALT within the editor cannot be indented or outdented using TAB or SHIFT + TAB.
  Workaround: Use Edit > Advanced > Increase Indent / Decrease Indent or select the lines using SHIFT and indent/outdent them line by line.
- ID 19270

  Renaming files does not update include statements.
  Description: In rare cases, renaming files may not correctly update the corresponding include statements within other files.
- ID 19492

  Renaming directories does not work.
  Description: In some cases, renaming folders that are part of a project has no effect.
- ID 19626

  Rename Symbol window displayed without contents.
  Description: In rare cases, the Rename Symbol function may open a results window that remains empty instead of listing the found references.
  Workaround: Repeat the rename operation.
- ID 19548

  IntelliSense window is minimized within the Watch List.
  Description: When entering a structure in the Watch List and typing a character after the first dot while using IntelliSense, the IntelliSense window may be minimized unexpectedly.
  Workaround: Re-enter the structure and navigate through the IntelliSense window using only the arrow keys.
- ID 19628

  OPC UA Server cannot be created.
  Description: If an OPC UA Client has already been created under the Connectivity node of the hardware tree, it is no longer possible to create an OPC UA Server afterwards.
  Workaround: Save the project, close it, and reopen it. The OPC UA Server can then be created.

- ID 19690

  Watch List becomes unusable after deleting all rows

  Description: If all entries in a Watch List are selected using CTRL + A and then deleted using CTRL + DEL, all rows, including the first one, are removed. As a result, no new values can be entered.

  Workaround: Close the Watch List window without saving and reopen it. When selecting rows, ensure that at least one row remains unselected.
- ID 19674

  I/Os are not displayed correctly in the Watch List.

  Description: If a new Watch List document is created and I/Os are added for monitoring while in offline mode, the TRUE/FALSE states are not displayed after going online.

  Workaround: Click on another cell with the mouse. The I/O status will then be displayed correctly.
- ID 19691

  Bit variables mapped to an EtherCAT PDO cannot be modified in the Watch List.

  Description: The state of bit variables that are mapped to an EtherCAT PDO during declaration cannot be changed in the Watch List using the +/- controls.
- ID 19273

  Freeze effect when connecting online with an incorrect controller IP address.

  Description: If an incorrect IP address is configured for the controller and an online connection is attempted, JetSym may become unresponsive for an extended period. During this time, JetSym cannot be operated.
- ID 19625

  Switching controllers may result in an exception.

  Description: If Motion Setup documents are still open when switching controllers, an exception may occur.

  Workaround: Close all Motion Setup documents before switching controllers.