BUCHER
automation

# Version Update



-

## Version update from 6.0.3 to 6.0.4

Bucher Automation AG has created this document with the requisite care and based on the current state of technology. Changes and further technical developments to our products are not automatically made available in a revised document. Bucher Automation AG shall accept no liability or responsibility for errors of content or form, missing updates or any damage or disadvantages arising therefrom.

**Bucher Automation AG**
Thomas-Alva-Edison-Ring 10
71672 Marbach/Neckar, Germany
T +49 7141 2550-0
info@bucherautomation.com

Technical support
T +49 7141 2550-444
support@bucherautomation.com

Sales
T +49 7141 2550-663
sales@bucherautomation.com

www.bucherautomation.com

Translation of the original document

Version: Version 1.00
Date of issue: 8/1/2025

# Table of Contents

**1 New additions ..... 4**
1.1 Memory Management ..... 4
1.1.1 Improved Memory Management ..... 4
**2 Fixed Software bugs ..... 5**
2.1 STX ..... 5
2.1.1 Overloaded methods caused crashes ..... 5
**3 Important notes ..... 6**
3.1 Installating JetSym ..... 6
3.2 .NET framework 4.7.2 ..... 6
3.3 CodeMeter runtime ..... 6
3.4 Motion API ..... 6
3.5 No support for TFS version control ..... 6

# 1 New additions

Below, all features newly included in this software version, as well as product enhancements are listed.

## 1.1 Memory Management

### 1.1.1 Improved Memory Management

JetSym 6.0.4 uses the compiler or linker option **Large Address Aware**. Large Address Aware (LAA) is a feature of 32-bit applications that allows them to address more than the standard 2 GB of memory. Under a 64-bit Windows operating system, LAA-enabled applications can use up to 4 GB of RAM.

# 2 Fixed Software bugs

This chapter describes the software bugs fixed in the new software release.

## 2.1 STX

### 2.1.1 Overloaded methods caused crashes

If overloaded methods were used in interfaces and/or in combination with virtual in STX, this could result in defective entries in the virtual method table. This caused the control or JetSym to crash when creating the list file.

# 3 Important notes

## 3.1 Installating JetSym

To be able to license JetSym during installation, the JetSym installation program must be started from an admin user account.

## 3.2 .NET framework 4.7.2

This JetSym release requires a .NET framework 4.7.2.

## 3.3 CodeMeter runtime

As of version 6.0.0 JetSym does no longer require the CodeMeter runtime.

## 3.4 Motion API

To use the Motion API in the new UTF-8 with BOM format, JetSym version 5.7.2 or newer is required.

## 3.5 No support for TFS version control

As of this version, version control is no longer supported with TFS 2010/2017.