Jetter automation



JXM-IO-E31

Version Update from V1.0.0.11 to V1.07.0.00

We automate your success.

Revision 1.20
February 2022 / Printed in Germany

This document has been compiled by Jetter AG with due diligence, and based on the known state of the art.

In the case of modifications, further developments or enhancements to products shipped in the past, a revised document will be supplied only if required by law or deemed appropriate by Jetter AG. Jetter AG shall neither be liable nor responsible for any errors in form or content, lacks in updating and possibly resulting damages or disadvantages.

The logos, brand names, and product names mentioned in this document are trademarks of Jetter AG, of associated companies or other title owners and must not be used without consent of the respective title owner.

Table of contents

1	**Changes to 1.07.0.0**	**4**
2	**Changes to 1.06.0.0**	**5**
3	**Changes to 1.05.0.0**	**6**
4	**Changes to 1.04.0.0**	**7**
5	**Changes to 1.00.0.11**	**8**

1 Changes to 1.07.0.0

Overview Version 1.07.0.00

The following table gives an overview of newly added or enhanced features and fixed software bugs:

Function	New	Enhanced	Fixed
Support for new Variant 2 with PT1000 measuring range up to 820°C			✓
HS3, HL5 & HL12: minimal PWM frequency lowered to 5Hz			✓
HL5 and HL12 ports: hardware protection – all outputs turned off if at least at on a current >55A or a temperature fault was detected			✓

2 Changes to 1.06.0.0

Overview Version 1.06.0.00

The following table gives an overview of newly added or enhanced features and fixed software bugs:

Function	New	Enhanced	Fixed
EMCY-message in case of total over current and supply voltage out of range			✓
HL5 and HL12 ports: hardware protection – all outputs turned off if at least at on a current >55A or a temperature fault was detected	✓		
Downgrade ability to 1.04.0.00 improved			✓

3 Changes to 1.05.0.0

Overview Version 1.05.0.00

The following table gives an overview of newly added or enhanced features and fixed software bugs:

Function	New	Enhanced	Fixed
HL5 & HL12: parameter OCD(65) = 1(at startup) not configurable anymore it's not supported by hardware			
All ports: status monitoring fixed			✓
CAN monitoring		✓	
Status LEDs control: bug fixes			✓
PT1000 port: temperature measurement linearization of raw values improved			✓
CAN-Busoff recognition: bug fixes			✓
Sensor voltage monitoring: bug fxes			✓
Heartbeat monitoring	✓		
HS3, HL5 and HL12 ports: current clip added if duty cycle is 0	✓		
DI ports: rotary encoder	✓		
PDO: bugfix for case that SDO and PDO handled at same time			✓
PDO mapping: bugfix in bitwise mapping			✓
DI: I_PeriodTime is calculated by I_HPulse and I_LPulse instead of _I_Frequency			✓
HS3: wind-up protection for current control		✓	
Support for new Variant 2 with PT1000 measuring range up to 820°C	✓		

4 Changes to 1.04.0.0

Overview Version 1.04.0.00

The following table gives an overview of newly added or enhanced features and fixed software bugs:

Function	New	Enhanced	Fixed
for PT1000 use linearization for raw values to compensate circuit dependent tolerances and non-linearity		✓	
Correct CRC returned on request at 0x4556 with sub index 1			✓
DI ports: timeout time default value changed to 1000ms			✓
DI ports: reset for input values if a timeout event occurs as in JXM-IO-E30			✓
DI ports: SDO read bug fixes			✓
EMCY messages: only send if port type isn't set to inactive			✓
CAN channel to send EMCY messages: wrong HW channel was used			✓
HS3, HL5 and HL12 ports: dither frequency maximum changed to 800Hz			✓
Port configuration: loading and use at startup fixed			✓
HL5 and HL12 ports: synchronized PWM ports' current monitoring independent: - I_HCURRENT holds current for asked port - Over current is monitored and signaled for each port separate			✓
CAN: thread priorities changed			✓
OS update: bug fixes			✓
HL5 and HL12 ports: PWM frequency handling for synchronized ports fixed			✓
During overcurrent cooldown phase status inactive is set	✓		
Input filter handling added	✓		
AI, HS3, HL5 and HL12 ports: current monitoring bug fixe for implicit type cast			✓
HS3, HL5 and HL12 ports: dithering fixed uses correct maximum value clip			✓
Open circuit detection at startup	✓		

5 Changes to 1.00.0.11

Overview Version 1.00.0.11

The following table gives an overview of newly added or enhanced features and fixed software bugs:

Function	New	Enhanced	Fixed
HS3, HL5 and HL12 ports: duty cycle handling bug fixes			✓
PT1000 port: temperature measurement bug fixes			✓
PT1000 port: set maximum for temperature to 150°C			✓
Diagnostics object: voltage divider implementation for VEXT_SEN adjusted			✓
HS3 ports: current control bug fixes			✓
DI ports: frequency input bug fixes			✓
AI ports: no over current detection in digital input mode			✓
HS3 ports: current measurement improved		✓	
AI ports: digital input hysteresis added	✓		
HS3 ports: added DI_PNP handling	✓		
AI, HS3, HL5 and HL12 ports: measuring tolerance			✓
HS3 ports: digital input handling			✓
HS3 ports: pull-up control			✓
HS3, HL5, HL12, AI and PT1000 ports: negative values handling			✓
Diagnostics object: PCB temperature measurement	✓		
Diagnostics object: total current calculation			✓
Diagnostics object: on-chip temperature calculation			✓
Calibration functionality added	✓		
HL5 and HL12 ports: improve current calculation		✓	
DI ports: interface type selection			✓
Software implementation for voltage divider corresponding to hardware 2.0			✓
Default values for synchronized HL5 and HL12 ports		✓	
Diagnostic object returns voltage VRef_Sen		✓	
Status LEDs control			✓

Jetter AG
Graeterstrasse 2
71642 Ludwigsburg | Germany

Phone +49 7141 2550-0
Fax +49 7141 2550-425
info@jetter.de
www.jetter.de

We automate your success.