BUCHER
automation

Version update



JX3-BN-EC
Version update from v1.10 to v1.14

Bucher Automation AG has created this document with the requisite care and based on the current state of technology. Changes and further technical developments to our products are not automatically made available in a revised document. Bucher Automation AG shall accept no liability or responsibility for errors of content or form, missing updates or any damage or disadvantages arising therefrom.

Bucher Automation AG
Thomas-Alva-Edison-Ring 10
71672 Marbach/Neckar, Germany
T +49 7141 2550-0
info@bucherautomation.com

Technical support
T +49 7141 2550-444
support@bucherautomation.com

Sales
T +49 7141 2550-663
sales@bucherautomation.com

www.bucherautomation.com

Translation of the original document

Version: 1.00
Date of issue: 7/15/2025

1 Fixed software bugs

1.1 Error in the detection of Jx3 bus errors

1.1.1 Behavior of version v1.10.0.00

JX3-BN-EC does not go into EC error state if a JX3 bus error occurs in OPERATIONAL.

1.1.2 New behavior from v1.14.0.00 onwards

The error behavior has been corrected.

1.2 Error in the process data behind JX3-CNT and JX3-MIX2

1.2.1 Behavior of version v1.10.0.00

If other modules were used behind modules of type JX3-CNT and JX3-MIX2, errors occurred in their process data.

1.2.2 New behavior from v1.14.0.00 onwards

The error behavior has been corrected.